

SECRET

PRIORITY

OUT52545

SECRET 302213Z

31 DEC 1963
25X1

1. CAMERA B 8 WAS USED IN MISSION 3803 FLOWN ON 29 DECEMBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THE FIRST 26 FRAMES ARE CRIMPED ALONG THE INBOARD EDGE. THERE IS A MANUFACTURER'S SPLICE IN FRAME 1119 AND FRAMES 1120 THROUGH 1123 CONTAIN NUMEROUS BLISTERS AND PINHOLES. A REPAIRED TEAR IS PRESENT IN FRAME 299 ADJACENT TO THE TAIL IDENT AND ANOTHER REPAIRED TEAR IS PRESENT IN FRAMES 2705/2706. THERE ARE HEAT SPLICES BETWEEN FRAMES 1380/1381, 2194/2195 AND 2707/2708.

Grace (File)

C. 9L SIDE: PLUS DENSITY STREAKS .10" FROM AND PARALLEL TO THE INBOARD EDGE AND 4.3" FROM AND PARALLEL TO THE OUTBOARD EDGE ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. MINUS DENSITY STREAKS AT AND PARALLEL TO THE INBOARD EDGE AND 4.1" FROM AND PARALLEL TO THE OUTBOARD EDGE OCCUR INTERMITTENTLY FROM HEAD TO TAIL. FRAMES 1220 AND 1554 CONTAIN MANUFACTURER'S SPLICES AND ASSOCIATED MINUS DENSITY SPOTS.

Declassification Review by NGA/DoD

25X1

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

2

D. THERE WERE NO CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES OTHER THAN THE USUAL MINOR PROCESSING STREAKS. THE IMAGERY IN A FEW OF THE FRAMES ARE SMEARED DUE TO VEHICLE ROLL. EXAMPLES: FRAMES 26 AND 1665. THE FIRST FRAME IS TITLED 0000 AND THE LAST FRAME IS TITLED 2969.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING OF THE PRINTS ARE GOOD.

B. CLOUDS COVER 80-85 PER CENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-